

*Remove the hose from the gun.*

*Install the 1/4" swivel adapter in the gun.*

*The gauge goes in the side port of the T, the brass valve goes on the male end of the T at a 90° angle to the gauge.*

*Install the surface cleaner hose in the bottom port of the brass valve, and the hose barb in the top port.*

*Attach the male threads of the T to the swivel adapter and tighten.*

*Drill a hole in the top of your deck just big enough to cram the hose barb through.*

*When you drill, avoid the ribs underneath.*

*Install the brass nut on the hose barb from underneath.*

*Attach tubing and clamps to the hose barbs.*